

# **Exhibit 49**



**Miyano Machinery Inc.**

940 N. Central Avenue  
Wood Dale, Illinois 60191  
Phone: (630) 766-4141  
Fax: (630) 860-7266

REPORTER: YARIC WATDA

DATE: 7/8/25

CUSTOMER: *ASI*

Tel: 570-669-2250

425 Appian Way

EL SOBRANTE, CA 94803

CONTACT PERSON: Michael Peterson

DEALER: CLANCY MACHINE (CA) Tel: (408) 991-9912

DATE	7/5	7/6	7/7	7/8		
HOURS WORKED	4	8	8	4		
HOURS TRAVEL	0	0	0	0		

SPECIAL OPTIONAL ATTACHMENT

**CUSTOMER P.O. NO.**

SERVICE REQ. BY	
-----------------	--

## MACHINE MODEL

SERIAL NO.	
------------	--

BND-42TR

BD70048P

## CONTROL MODEL

CONTROL S/N	
-------------	--

FANUC 18-1

SPINDLE DRIVE

INVERTOR S/N	
--------------	--

- ① NEW INSTALLATION ② TEST CUTTING  
③ INSTRUCTION 4. ELECTRIC TROUBLE SHOOT  
⑤ ALTER SET-UP 6. REPLACEMENT PARTS  
7. ADJUSTMENT 8. CHECK-UP 9. REPAIR  
10. DISASSEMBLE 11. ASSEMBLE 12. OTHER

## WARRANTY

YES ☒ NO ☐

SERVICE REQUESTED INITIAL SET-UP & TRAINING FOR PND 42K

SERVICE PERFORMED Assisted Charlie from Clancy Machine  
in SET-UP AND TRAINING CUSTOMER. Pick-off  
Chuck is leaking so we tried to  
fix but were not successful. Chicago agrees  
to send new replacement ASAP. Other than pick-off  
Chuck machine is functioning properly.

Q'TY.	PART NO.	PART NAME	UNIT PRICE	TOTAL PRICE
PRESIDENT OF COMPANY:		OWNER OF COMPANY:		
PROGRAMMER	SET-UP	FOREMAN	POSSIBILITY OF NEXT MACHINE	

SERVICED BY: (Serviceman Signature)

APPROVED BY: (Customer Signature)

MMU0017558

# SERVICE REPORT



Miyano Machinery Inc.

484420

940 N. Central Avenue  
 Wood Dale, Illinois 60191  
 Phone: (630) 786-4141  
 Fax: (630) 860-7268

REPORTER: DK1 / MARK

DATE: 08/18/03

CUSTOMER: Wolverine Machine Tool (248) 634-9952

319 Cogshall St

Holly MI 48442

CONTACT PERSON: Jeff, Chuck, ED CHANDLER

CUSTOMER P.O. NO.	SERVICE REQ. BY
MACHINE MODEL L2-D/R	SERIAL NO. L21R0430~33
CONTROL MODEL 21-1th	CONTROL S/N 21111 Sec 8/11/03
SPINDLE DRIVE	INVERTOR S/N

DEALER:

STATE ( ) Tel:

DATE	8/18	8/19	8/20	8/21	8/22	8/23
HOURS WORKED	6H	12H	8H	10H	10H	6
HOURS TRAVEL	5H		5H/5H			

SPECIAL OPTIONAL ATTACHMENT

OKI mtd.

- ☒ NEW INSTALLATION ☐ 2. TEST CUTTING  
 3. INSTRUCTION 4. ELECTRIC TROUBLE SHOOT  
 5. ALTER SET-UP 6. REPLACEMENT PARTS  
 7. ADJUSTMENT 8. CHECK-UP 9. REPAIR  
 10. DISASSEMBLE 11. ASSEMBLE 12. OTHER

WARRANTY

YES ☒ NO ☐

SERVICE REQUESTED NEW INSTALLATION / SET UP / Program / Train

SN# L21R0430	FAVOR SN# E024A0394	SN# L21R0432	FAVOR SN# E024A0119
L21R0431	E024A0395	L21R0433	E024A0118

SERVICE PERFORMED 4 new machines are leveled.  
 All functions (machine, loader) are checked.  
 Other 4 machines (L21R417, 427, 428, 429) are re-leveled.  
 L21R431, 433 got a low battery alarm. They are re-taught turret pos.  
 L21R432 needed to be re-taught turret pos, 1 = done

Q'TY.	PART NO.	PART NAME	UNIT PRICE	TOTAL PRICE

PRESIDENT OF COMPANY:	OWNER OF COMPANY:
PROGRAMMER	POSSIBILITY OF NEXT MACHINE
SET-UP	
FOREMAN	

SERVICED BY: (Serviceman Signature)

APPROVED BY: (Customer Signature)